Submit One Copy To Appropriate Cares OCD State of New Mexico Office Energy Minerals and Natural Resources	Form C-103
District I 1625 N. French Dr., Hobbs, NM 8240 0 8 2016 District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis Dr.	Revised November 3, 2011 WELL API NO. 30-025-05298
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. Sonto Fo. NIM 87505	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lagge Name of Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Denton
PROPOSALS.) 1. Type of Well: ⊠Oil Well □ Gas Well □ Other	8. Well Number 11
2. Name of Operator	9. OGRID Number
Fasken Oil and Ranch, Ltd.	151416 10. Pool name or Wildcat
3. Address of Operator 6101 Holiday Hill Road, Midland, TX, 79707	Denton; Wolfcamp
4. Well Location	
Unit Letter B: 660 feet from the North line and 1815 feet from the Eastline	/
Section 11 Township 15S Range 37E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
 ⊠ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. ∆ Steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
140	
SIGNATURE TITLE Regulatory Analyst TYPE OR PRINT NAME Addison Long E-MAIL: addison@forl.com	DATE 12/6/16 PHONE: 432-687-1777
For State Use Only	
APPROVED BY: Mah Whitstam TITLE P.E.S. Conditions of Approval (if any):	DATE 1/4/2017