District I 1625 N. French Dr., Hobbs, NM 88240

## State of New Mexico Energy Minerals and Natural Resources

Form C-129 Revised October 15, 2009

District III

1000 Rio Brazos Road. Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87503

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87503

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87503

NFO F

Submit one copy to appropriate District Office

NFO Permit No. \_\_\_ (For Division Use Only)

## APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

Α.	Applicant Occidental Permian LTD ,		
	whose address is1017 W Stanolind Road, Hobbs, NM 88240,		
	hereby requests an exception to Rule 19.15.18.12 for17days or until		
	Friday the 17th, Yr2017, for the following described tank battery (or LACT):		
	Name of Lease NHU 24 C Satellite Name of Pool G/SA		
	List Location of Battery: Unit LetterO Section24Township18-SRange _38-E		
	Number of wells producing into battery21 wells		
B.	Based upon oil production ofN/Abarrels per day, the estimated * volume		
	of gas to be flared is250MCF; V	alueper day.	
C.	Name and location of nearest gas gathering facility:		
NHU WIB/RCF PLANT			
D.	Distance1/2 mileEstimated cost of connection		
E. This exception is requested for the following reasons: Facility and Construction will be bleeding down the a 10" gas gathering line coming from NHU 24C satellite, to make repairs on a collapsed liner. Due to bleeding down the gas gathering line, there will be a flare at the NHURCF plant. Work will start on 2-2-17 at 7am and post till 2-17-17.			
OPERATOR		OIL CONSERVATION DIVISION	
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		Approved Until 2/17/2017	
Signature Intel Service Signature		By Mader Brown	
		By Mary Down	
Printed Name & Title Tony Aguilar (HES Specialist)		Title AO/1/	
E-mail Addre	ess raymond aguilar@oxy.com	Date 1/24/2017	
Date 1-24-1	7 Telephone No. <u>575-397-8251</u>		

Gas-Oil ratio test may be required to verify estimated gas volume.

30-025-07357 \_\_\_ NHSAU 121-19

Well Name Last NHSAU 121-30 NHSAU 141-24 NHSAU 221-23 NHSAU 221-24 NHSAU 231-24 NHSAU 311-23 NHSAU 311-24 NHSAU 331-23 NHSAU 412-24 NHSAU 421-24 NHSAU 421-25 NHSAU 441-24 NHSAU 516-13 NHSAU 611-24 NHSAU 612-24 NHSAU 613-24 NHSAU 614-24 NHSAU 615-19 NHSAU 617-30 NHSAU 641-25 NHSAU 646-13 NHSAU 663-24 NHSAU 731-25 NHSAU 211-24 NHSAU 241-24 NHSAU 321-24 NHSAU 341-24 NHSAU 411-24 NHSAU 421-23 NHSAU 441-23 NHSAU 539-24 NHSAU 549-24

NHSAU 673-19