Submit 1 Copy 10 Appropriate District Office State of New Mexico District I – (575) 393-616 HOBBS OF Pregy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 Minerals and Natural Resources District II – (575) 748-1283 IAN 2 5 2017 OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. District IV – (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					Form C-103 Revised July 18, 2013 WELL API NO. 30-025-42207 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. NM 0149956 7. Lease Name or Unit Agreement Name N/A	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: Acid Gas Injection					8. Well Number	
2. Name of Operator					9. OGRID Number	
DCP MIDSTREAM LP 3. Address of Operator 370 17 TH STREET, SUITE 2500, DENVER, CO 80202					025575 10. Pool name or Wildcat DEVONIAN EXPL.	
4. Well Location						
Uni	it Letter <u>L</u> :	feet from	the South	line and950	feet from the	West_line
Sec	tion	19 Town	how whathar D	Range 32	2E NMPM	County LEA
3548 ft. Ground Level						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE COMMINGLE COTUED OF SYSTEM					SEQUENT REPO K AL' LLING OPNS. P A r JOB D	RT OF: TERING CASING AND A
OTHER: OTHER: OTHER: Subsequent MIT and Bradenhead						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
The MIT and Braden head Test were conducted on Wednesday, January 2,7 2017 at 8:18 am. In order to conduct the MIT, the annular space pressure was adjusted to 560 psig by adding a small amount of diesel immediately before the test.						
 Initially the starting injection pressure and the annular space pressure between casing and tubing was 280 psig Placed chart on annular space and began recording annular space pressure. Bled off annular fluid (diesel) to bring observed annular space pressure to zero psig. Slowly raised annular pressure by introducing diesel to the annulus to bring pressure to 560 psig. When annulus pressure reached 560 psig closed valves to pumping truck and recorded annular space pressure for 30 minutes. The DCP Zia AGI D #2 is not yet in service so there is no injection pressure on the tubing. After 30 minutes bled off annular fluid to reduce observed pressure to zero psig. Stopped recording TEST COMPLETE. Restored annular pressure to normal psig. 						
The Braden head Test was conducted concurrent with the MIT, which included bleeding off the pressure and keeping the valve open during the MIT.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
Spud Date:	November 2, 201	16	Rig Release D	ate:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE						
Type or print : For State Use	name JA	RED R. SMITH	_ E-mail addres	ss:JSMITH@G	EOLEX.COM_ PHO	NE: <u>505-842-8000</u>
APPROVED BY. Jog Brance TITLE Compliance Officer DATE 1/25/2019						

