

## FLARE INSPECTION

LEASE OR FACILITY NAME Devon New Mexico Fed. Com.

WELL # 3H API# 30-025 - 39741

U.L. A SEC 24 T 18s R 33E

FOOTAGE 510 N/S 545 E/W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS \_\_\_\_\_

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS \_\_\_\_\_

INSPECTOR Gary Roberson DATE 3-9-17