

FLARE INSPECTION

EOGY

LEASE OR FACILITY NAME Mamba "B&N" St. Com

WELL # 1H API# 30-025-40039

U.L. N SEC 30 T 24s R 33E

FOOTAGE 330 N / (S) 1980 E / (W)

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS _____

INSPECTOR Gary Robinson DATE 3-13-17

SALES

Trunk