

FLARE INSPECTION

Newbourne

LEASE OR FACILITY NAME *SALADO URGW 9 A3CN*

WELL # *1H* API# 30- *025* - *42437*

U.L. *C* SEC *9* T *26S* R *33E*

FOOTAGE *305* *N*/S *2355* E/*W*

IS A FLARE STACK PRESENT? YES ☒ NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS *Comp. on sales line*

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES NO

COMMENTS

INSPECTOR *Larry Robinson* DATE *3-28-17*