

FLARE INSPECTION

Matador
LEASE OR FACILITY NAME Young Deep Unit
WELL # 34 API# 30-025-31467
U.L. 0 SEC 9 T 185 R 32E
FOOTAGE 330 N (S) 1915 (E) W
IS A FLARE STACK PRESENT? (YES) NO
IS FLARE ACTIVE? YES (NO)
IS GAS TO FLARE METERED? (YES) NO
AREA AROUND FLARE CLEARED? (YES) NO
ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES (NO)
IS VRU ACTIVE? YES NO

COMMENTS _____

INSPECTOR Gary Robinson DATE 4-24-17