

FLARE INSPECTION

COG
LEASE OR FACILITY NAME Lusk Deep Unit A

WELL # 23H API# 30-025 - 40260

U.L. P SEC 19 T 19s R 32e

FOOTAGE 330 N/O 330 (E) W

IS A FLARE STACK PRESENT? ☒ YES NO

IS FLARE ACTIVE? ☒ YES NO

IS GAS TO FLARE METERED? ☒ YES NO

AREA AROUND FLARE CLEARED? ☒ YES NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES NO

COMMENTS Has flare on vapor and burning

INSPECTOR Gary Robinson DATE 4-21-17

HOBBS OCD

APR 24 2017

RECEIVED