

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

HOBBS OCD  
 APR 21 2017  
 RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-34964
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 541

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
A	32	18-S	38-E	887	NORTH	586	EAST	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
		<input checked="" type="checkbox"/>	4-10-17

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	e			400	400
Flow Characteristics					
Puff	<input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Y / N
Surges	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Y / N
Down to nothing	<input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Y / N
Water	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

Surface bleed down to zero. By 4-10-17 575-447-9739

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test 
E-mail Address: mendy_johnson@oxy.com	
Date: APR 19 2017	Phone: 806-592-6280
Witness:	