District 1 I 625 N. French Dr., Hobbs. NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 State of New Mexico HODES 0.2011 State of New Mexico HODES 0.2011 Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT 2400 Number										
HO	BRADENHEAD TEST REPORT									
MAT	MAT SEIVED A Dache Corp. 30					30 -	-025-05648			
RE	Property Name NIMGSAU							Well No. 515		
^{7.} Surface Location										
UL - Lot	Section Township	Range 37E			Feet from	N/S	Line	Feet From	E/W Line	County 209
Well Status										
YES TA'D	MO YE	SHUT-IN	NO (ÎNJ)	INJECTOR	SWD	OIL	RODUCER GA	s 5-	DATE 5-17

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0	WIA	D	730
Flow Characteristics				0	
Puff	Y /	YA	Y / N	YUN	CO2
Steady Flow	YIN	YIN	YIN	YN	GAS
Surges	Y I N	YIO	Y/N	Y /N	Type of Fluid
Down to nothing	(IN .	Ox	Y/N	() N	Injected for WaterBood if
Gas or Oil	YIN	Y IN	Y/N	YN	opplies
Water	YIN	YN	Y/N	YAN	

Demonstry Discourse for each string (A.D. (J.D. E) contingent information recording bland down on continuous build up (Fourties					
Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.					
		• *			

Signature:	QD Ellion	OIL CONSERVATION DIVISION
Printed name:	Jim Ellison	Entered into RBDMS
Title:	Instrument Tech	Re-test
E-mail Address:	JDi Ellison @ apache comp. com	UX4
Date:	Phone: 575-4417734	
	Witness: Muy holmson	