State of New Mexico

Energy, Minerals and Natural Resources DepartmentOil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Property Name NORTH HOBBS (G/SA) UNIT											30-025-34871		
Property Name NORTH HOBBS (G/SA) UNIT											Well No. 813		
7. Surface Location													
UL - Lot L			ownship Range 18-S 38-E		Feet from 1450			N/S Line SOUTH		From 69	E/W Line WEST	County	
L 29 16-5 36-E					Well Status			7	09	WEST	LEA		
Well Status SHUT-IN PRODUCING DATE													
well Status				NO	3			6/1/17					
	OPE	N BR	ADENH	EAD AND INT	ERMED	IATE TO ATMOSP	HERE IND	IVIDUALI	LY FOR 1	5 MINUT	TES EACH		
If bradenhead	flowed wa	ter, c	heck all o	of the descriptio	ns that a	OBSERVED I	DATA						
				(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure	Pressure			0		NIA		N/A		330		1064	
Flow Characteristics													
Puff			YIO		Y/N			Y/N		Y / 🛇			
Steady Flow			Y A		Y / N			Y/N		(Y/N Y/(S)			
Surges Down to nothing			Q/N		Y/N Y/N			Y/N Y/N		(Y)/ N			
Gas or Oil			YIN		Y/N		_	Y/N		Y/®		-	
Water		YI		Y/N		-	Y/N		Ø/ N		-		
											_		
If bradenhead flowed water, check all of the descriptions that apply:													
CLEAR			FRES			SALTY		SULFUR		BLACK			
Remarks: D - black			,		ast	endy flow of			THIST	ME	WTR,GA	S,CO2	
Signature: OA H. d. ORO & OO OO									OI	OIL CONSERVATION DIVISION			
Printed some MENDY JOHNSON									Entered into RBDMS				
Printed name: MENDY JOHNSON Title: ADMINISTRATIVE ASSOCIATE									Re-test 2				
E-mail Address: mendy_johnson@oxy.com									-10 1001		1	1	
Date: BUI	TOPAL 1 9 201		1	Phone: 806-5	92-6280	2-6280					\wedge		
				Witness:							· · · · · · · · · · · · · · · · · · ·		