<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210

District III

HOBBS OF State of New Mexico

Oil Communication of New Mexico

Oil Communication of New Mexico JUN 16 2017 1000 Rio Brazos Road, Aztec, NM 87410

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

RECEIVED 1220 S. St. Francis Dr., Santa Fe, NM 87505

NFO Permit No. (For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

A.	ApplicantMurchison Oil & Gas, Inc.	,
	whose address is7250 Dallas Parkway, Ste. 1400, Plano, TX 75024,	
	hereby requests an exception to Rule 19.15.18.12 for days or until <u>September 20</u> ,	
	, Yr <u>2017</u> , for the following described tank battery (or LACT):	
	Name of Lease <u>Jackson Unit 16H (30-025-41167)</u> Name of Pool <u>Triple X; Bone Spring, West</u>	
	Location of Battery: Unit LetterBS	ection15Township24SRange33E/
	Number of wells producing into battery	<u>2</u>
В.	Based upon oil production of40_	barrels per day, the estimated * volume
	of gas to be flared isMCF	; Valueper day.
C.	Name and location of nearest gas gathering f	acility:
	Frac Cat Compressor Station, Lea County, N	<u>M</u>
D.	DistanceEstimated cost of connection	
E.	This exception is requested for the following reasons: <u>Intermittent curtailment by Lucid due to</u> compressor maintenance. Well shut in at this time may damage formation and reduce future production.	
		OIL CONSERVATION DIVISION
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief Approved Until		
is true and complete to the best of my knowledge and belief.		
Signature Lay Cooper les C. Cette By		By Maleur Brown
Printed Name		10/11
& TitleGary Cooper, Vice President Operations		Title
Email Address rcooper@jdmii.com		Date 6/20/2017
Date 06/13/	17 Telephone No. 972-931-0700	
* Cas Oil ratio test may be required to varify estimated ass volume		

Gas-Oil ratio test may be required to verify estimated gas volume.