Submit One Copy To Appropriate District State o	f New Mexico	Form C-103
District I Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.
District II		30-025-06650
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 AUG 0 4 24220 South St. Francis Dr.		STATE FEE
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVED RECEIVED		6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)		MITTIE WEATHERLY 8. Well Number 4
1. Type of Well: Oil Well Gas Well Other		
2. Name of Operator CHEVRON USA INC	/	9. OGRID Number / 4323
3. Address of Operator		10. Pool name or Wildcat
6301 DEAUVILLE BLVD MIDLAND, TX 79706		GRAYBURG
4. Well Location		
Unit Letter <u>E</u> : <u>1980</u> feet from the <u>NORTH</u> line and <u>660</u> feet from the <u>WEST</u> line		
Section 17 Township 21S Range 37E NMPM County LEA		
11. Elevation (Show v 3477'	whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		ГЈОВ
		Bur
OTHER:       Image: Construction of the constr		
<ul> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> </ul>		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Cint Honore Murillo	TITLE PERMITTING SPE	<u>CIALIST</u> DATE08/03/2017
TYPE OR PRINT NAME CINDY HERRERA-MURILLO	E-MAIL: <u>EEOF @CHEVE</u>	RON.COM PHONE: <u>575-263-0431</u>
For State Use Only		
APPROVED BY: Machinitaten	TITLE YES.	DATE 08/07/20/7

Conditions of Approval (if any):