| Submit 1 Copy To Appropriate District State of New Mexico Office District 1 – (575) 393-6161 Energy, Minerals and Natural Resource | Form C-103 Revised July 18, 2013 |
|---|--|
| 1625 N. French Dr., Hobbs, NM | WELL API NO. |
| District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 AUG 2 1 2017 1220 South St. Francis Dr. | 30-025-24312 5. Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NRECEIVED 87505 | 0. State off a Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT |
| 1. Type of Well: Oil Well Gas Well Other INJECTOR | 8. Well Number 34 |
| 2. Name of Operator CHEVRON U.S.A. INC. | 9. OGRID Number 4323 |
| Address of Operator 6301 DEAUVILLE BLVD, MIDLAND, TX 79706 | 10. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES |
| 4. Well Location | |
| Unit Letter J :2630feet from theSOUTH line : Section 1 Township 18-S Range | and2630feet from theEASTline // 34-E NMPM County LEA |
| 11. Elevation (Show whether DR, RKB, RT, G | |
| 4,011' (GL) | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL | WORK ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB | |
| | |
| CLOSED-LOOP SYSTEM CONTHER: REPLACE PACKER CONTHER: | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | |
| | |
| The VGSAU 34 was shut-in after identifying a casing leak from 840-870' during an injection profile survey. Below is the proposed repair procedure, current WBD, and proposed WBD. | |
| MIRU, kill well with red bed mud. NU BOP. | |
| Release Loc-Set Packer and POOH laying down 2-3/8" duoline tbg and packer. | Condition of Approval: notify |
| RIH w/ bit and C/O to PBTD @ 4799'. TIH w/ 5-1/2" CIBP and test RBP set at ~4220'. Dump bail 20' of cement on CIBP. | |
| MIRU wireline, perform logging run with iso-scanner/GR/CNL tool from 4150' to surface. prior of running MIT Test & Chart | |
| Set RBP @ 2000' and perform wellhead work for liner. Remove RBP RIH w/ 4" 11# L-80 FJ liner to 4170'. RU cementers and cement in with class C cement. | |
| P/U 3-1/4" bit and drill out cement, continue cleaning out to PBTD @ 4799'. RIH w/ packer and set @ ~4160'. RIH w/ TK-99 injection tubing. Pump packer fluid and test backside. RTI pending successful MIT. | |
| rent w packet and set a 4100 . Rent w 1R-99 injection tubing. I drip packet hard and test backside, Rent pending successful with. | |
| Spud Date: Rig Release Date: | |
| | |
| I hereby certify that the information above is true and complete to the best of my kno | weldge and heliof |
| Thereby certify that the information above is that and complete to the best of my knowledge and bench. | |
| SIGNATURE TITLE_Production EngineerDATE8/14/17 | |
| Type or print name _Michael Stewart E-mail address:michael.stewart@chevron.comPHONE: _432-687-7431 | |
| APPROVED BY: Maley Brown TITLE AO/II DATE 8/21/2017 Conditions of Approval (if any) | |
| Conditions of Approval (it may | AR |
| | |



