

## FLARE INSPECTION

*MACK Energy*

LEASE OR FACILITY NAME

*CAP ST. #1*

WELL #

*#1*

API# 30-

*025 - 40920*

U.L.

*J*

SEC

*18*

T

*18s*

R

*34E*

FOOTAGE

*22605*

N/S

*1425*

E/W

IS A FLARE STACK PRESENT?

☒ YES

NO

IS FLARE ACTIVE?

YES

☒ NO

IS GAS TO FLARE METERED?

YES

☒ NO

AREA AROUND FLARE CLEARED?

☒ YES

NO

ENVIRONMENTAL CONCERNS

*Flare not burning - gas going to sales.*

IS VRU PRESENT?

YES

☒ NO

IS VRU ACTIVE?

YES

☒ NO

COMMENTS

*Batt. has combustor and is burning tank vapors*

INSPECTOR

*Mary Robinson*

DATE

*9-11-17*