## FLARE INSPECTION

COG LEASE OR FACILITY NAME <u>Csprey</u> 20 ST. Com WELL # 3H \_\_\_\_\_API# 30-025- 40969 U.L. K SEC 20 T 2/S R 34E FOOTAGE 2590 N/S 1680 E/W IS A FLARE STACK PRESENT? YES NO NO IS FLARE ACTIVE? IS GAS TO FLARE METERED? YES NO AREA AROUND FLARE CLEARED? (YES) NO ENVIRONMENTAL CONCERNS Flare not burning, gas going to sales (NO IS VRU PRESENT? YES IS VRU ACTIVE? YES NO COMMENTS Has active combuster Vgpas INSPECTOR Baus Kolonso DATE 9-15-17