Submit 1 Copy To Appropriate District Office	State of New Me	exico		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	iral Resources	Rev WELL API NO.	vised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-025-41	1767
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE 🛛 F	FEE 🗌 🗡
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM o	1005 No 100	6. State Oil & Gas Lease N	No.
87505	ICES AND REPORTS ON WELLS	Or Elle	7. Lease Name or Unit Ag	recoment Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK O A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCK			JACKSON UNIT	
PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other			8. Well Number 029H	¥
2. Name of Operator     MURCHISON OIL & GAS, INC.			9. OGRID Number 15363	3
				· · · · · · · · · · · · · · · · · · ·
<ol> <li>Address of Operator 7250 DALLAS PARKWAY, STE. 1400, PLANO, TX 75024</li> </ol>			10. Pool name or Wildcat TRIPLE X; BONE SPRING, WEST	
4. Well Location	THE LE X, DOILE STRIK	G, WLOI		
Unit Letter O :	200 feet from the SOU'	TH line and 16'	$\underline{70}$ feet from the $\underline{E}$	AST line
Section 21	Township 24S	Range 33E	NMPM LEA	County
	11. Elevation (Show whether DR			
	3529 GR			
12 Check	Appropriate Box to Indicate N	lature of Notice	Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	SEQUENT REPORT			
TEMPORARILY ABANDON     CHANGE PLANS     COMMENCE DRI       PULL OR ALTER CASING     MULTIPLE COMPL     CASING/CEMENT				
		CASING/CEMEN		
CLOSED-LOOP SYSTEM				
OTHER:			MIT & Request TA Status	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or rec		c. For Waitiple Cor	inpletions. Attach wendore t	Inagranii Or
10/5/17 D: 1 10 D				
10/5/17: Rigged up L&E pump truck and loaded well with 1 bbl of fresh water. Pressure tested casing to 600 psi for 32 minutes with 1000# chart recorder; pressure dropped to 560 psi; passed test. Gary Robinson, OCD, witnessed test and signed pressure chart.				
			essea test and signed pressu	e entre.
We hereby request TA status for one year.				
This Approval of Temporary				
Abandonment Expires 10/5/2018				
Proventie of the office of the				
Spud Date: 07/21/2015	Rig Release D	ate: 08/16/2015		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	1			
SIGNATURE	TITLEVice	President Operation	DATE <u>10/16/17</u>	7
Type or print name: Gary Cooper E-mail address: rcooper@jdmii.com PHONE: 972-931-0700				
For State Use Only				
APPROVED BY: Wale	4 DIOWATELE	AOIL	DATE IC	)/22/2017
Conditions of Approval (if any):		per	DATE	100/0001
	U	-		
RBDMS- CHART-V				
	KBDM5- Ch	THE -V		

