

FLARE INSPECTION

Oxy

LEASE OR FACILITY NAME Lusk 28 West Fed. Com

WELL # #114 API# 30-025 - 41257

U.L. 0 SEC 29 T 19s R 326

FOOTAGE 652 N (S) 2425 (E) W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS Gas going to sales

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS Tank vapor has combustor

INSPECTOR Gary Robinson DATE 10-24-17