Submit One Copy To Appropriate District	State of New M	exico	Form C-103
Office District I	Energy, Minerals and Nat	ural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	*10	BBS	WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION		30-041-20416 5. Indicate Type of Lease
District III	1220 South St. Fra	hos Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505 2017	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	REC	Elve	
87505 SUNDRY NOTIC	CES AND REPORTS ON WELL	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN OR PI	LUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	ATION FOR PERMIT" (FORM C-101) F	OR SUCH	Roberts
1. Type of Well: \(\sum Oil Well \subseteq 0	Gas Well Other		8. Well Number #1
2. Name of Operator			9. OGRID Number
Saber Oil & Gas Venture, LLC	/	^	243978
3. Address of Operator	T. 50501		10. Pool name or Wildcat
400 W. Illinois, Suite 940, Midland	1x 79701		Chaveroo Canyon, North
4. Well Location			
Unit Letter D: 660 feet from the North line and 660 feet from the West_line			
Section 9 Township 7S Range 33E NMPM Roosevelt County NM			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4386' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
	_		
OTHER:			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
TERMANENTEL STAIM ED ON THE MARKER STURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.			
☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
7/4/2/18 De 1/2/19			
SIGNATURE //95/49	TITLE	Uperas	ONS DATE 1923//7
TYPE OR PRINT NAME NE	Spalatton E-MAIL	,	PHONE: 432)685-0169
For State Use Only			
A I (Hy 1-	P.E.S.	DATE 10/30/2017
APPROVED BY: Vlahlu	TITLE_	100	DATE