Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-025-27845
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
District IV – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	Hone		
	ICES AND REPORTS ON WEL	GOBBS OCI	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Langlie Jal Unit
PROPOSALS.)	O NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A FERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR STCH 02017		•
1. Type of Well: Oil Well	Gas Well Other		8. Well Number 100
2. Name of Operator	,	RECEIVED	9. OGRID Number <b>372000</b>
Pogo Oil & Gas Operating, Inc.			10. Paul
3. Address of Operator 1515 Calle Sur, Ste 174 Hobbs, N	New Mexico 88240 USA		10. Pool name or Wildcat  Langlie Mattix
4. Well Location	TEW MEXICO 60240 USA		Langue Wattix
1	1426 feet from the	S line and	300 feet from the W line
Section 32		Range 37E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3235			
12. Check	Appropriate Box to Indicate	Nature of Notice,	Report or Other Data
NOTICE OF IN	ITENTION TO:	CLID	SECUENT BEDORT OF:
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			SEQUENT REPORT OF:  K □ ALTERING CASING □
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	
PULL OR ALTER CASING			
CLOSED-LOOP SYSTEM	1 ,		
OTHER:	OTHER: X RETURN TO PRODUCTION		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Summary: Langlie Jal Unit #100 was returned to production on 10/17/17. 4 tbg jts were replaced due to pitting and the pump was also			
rebuilt. Pogo Oil & Gas Operating, Inc. respectfully requests this well to be reclassified as an active producer. Well test estimates initial			
production at 2 BOPD and 180 BWPD.			
Procedure (as it occurred 10/16/17-10/17/17):			
1) Test Anchors. AOL. ND WH, NU BOP. RU WO rig.			
2) POOH w/ rods and pump. LD pump, stand back rods.			
3) POOH w/2-7/8" tbg.  4) PUL with my/the while hydrotesting to 5000 me helevy the cline. 4 its foiled replaced with new the from yord.			
<ol> <li>RIH with w/ tbg while hydrotesting to 5000 psi below the slips. 4 jts failed, replaced with new tbg from yard.</li> <li>RIH w/ replacement pump and rods.</li> </ol>			
6) Check for good pump action.			
7) ND BOP, NU WH.			
8) Clean location, RD WO unit, move out			
Spud Date:	Rig Release	Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Operations Manager DATE 10/25/17			
Type or print name: Kyle Townsend E-mail address: kyle@pogoresources.com PHONE:713-305-9886			
For State Use Only			
APPROVED BY: DATE O SU PITLE DATE			
Conditions of Approval (if any)!			, ,