

## FLARE INSPECTION

Deron

LEASE OR FACILITY NAME Stray Cat 8 Feel. Com

WELL # 1H API# 30-025 - 42982

U.L. M SEC 8 T 23s R 32E

FOOTAGE 211 N (S) 660 E (W)

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? YES (NO)

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

ENVIRONMENTAL CONCERNS Well on comp. Both has metered flare  
(not in use) 2-Comp pushing Tank Vapors.

IS VRU PRESENT? (YES) NO

IS VRU ACTIVE? YES NO

COMMENTS Tank vapor going to comp.

INSPECTOR Gary Robinson DATE 11-7-17