

FLARE INSPECTION

Cimarex

LEASE OR FACILITY NAME Witherspoon 26-23 ST #1H

WELL # 1H API# 30- 025 - 43291

U.L. M SEC 26 T 2/s R 33E

FOOTAGE 330 N / S 630 E / (W)

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? (YES) NO

IS GAS TO FLARE METERED? (YES) NO

AREA AROUND FLARE CLEARED? (YES) NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? (YES) NO

IS VRU ACTIVE? (YES) NO

COMMENTS _____

INSPECTOR Gary Robinson DATE 12-12-17