

FLARE INSPECTION

Matador

LEASE OR FACILITY NAME Eland 32 18 33 RN ST

WELL # 123 H API# 30- 025 - 42977

U.L. P SEC 32 T 18s R 33e

FOOTAGE ~~405~~ 465 N / ⑤ 1195 ⑤ W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS Gas going to sales

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS

Has combustor on Tank vapors

INSPECTOR Larry Robinson DATE 1-3-18