HOBBS OCD

Submit 3 Copies To Appropriate District State of New Mexico JAN 16	2018 Form C-103
Office Energy, Minerals and Natural Resources	October 25, 2007
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO. 30-025-02711
1301 W. Grand Ave., Artesia, NM 88210 1220 South St. Francia Dr.	5. Indicate Type of Lease
District III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505	STATE XX FEE /
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	27811
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State D
PROPOSALS.)	8. Well Number
1. Type of Well: X Oil Well Gas Well Other	002 /
2. Name of Operator	9. OGRID Number
Energen Resources Corporation	162928
3. Address of Operator	10. Pool name or Wildcat
3510 N. "A" St., Bldgs A & B, Midland, TX 79705	Wolfcamp
4. Well Location	TOWNSER D: PERMO UPPER PENH
Unit Letter L 1980 feet from the South line and 330	feet from the line
Section 1 Township 16S Range 35E NMPM	County Lea, New Mexico
11. Elevation (Show whether DR, RKB, RT, GR, etc	
3992' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other I	Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT J	
OTHER: 🗌 🛛 Location is rea	dy for OCD inspection after P&A ?
All pits have been remediated in compliance with OCD rules and the terms of the Ope	the second se
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below grou	ind level.
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produ	action equipment and junk have been removed
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been rem	oved. (Poured onsite concrete bases do not have
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b)	NMAC. All fluids have been removed from
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to sch	
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
Brenda F. Rathjen Bollastyer 432-688-3323 1911B SIGNATURE Tommy Gose TITLE Assistant Production	Legulatory Analys
SIGNATURE / BINDING (ABAR)	Superintendent DATE 1/9/12
SIGNATORE INCE	DATE
TYPE OR PRINT NAME Tommy York E-MAIL_tommy.york@ener	
TYPE OR PRINT NAME Tommy York E-MAIL tommy york@ener	gen.com PHONE
TYPE OR PRINT NAME Tommy York E-MAIL tommy york@ener	