

FLARE INSPECTION

Centennial Resources

LEASE OR FACILITY NAME Merchant Livestock 25 ST. Com.

WELL # 1 H API# 30- 025 - 40935

U.L. D SEC 25 T 225 R 34E

FOOTAGE 20 (N) S 380 E (W)

IS A FLARE STACK PRESENT? YES (NO)

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS _____

IS VRU PRESENT? YES (NO)

IS VRU ACTIVE? YES NO

COMMENTS 2 batteries on location - / combustor
taking tank vapors off of both batteries

INSPECTOR Gary Robinson DATE 1-16-18