FLARE INSPECTION

Centenial Resources LEASE OR FACILITY NAME God father 36 ST. Com
WELL # 2 H API# 30-025 - 41353
U.L. C SEC 36 T 225 R 34E
FOOTAGE 40 (N) S 1670 E (W)
IS A FLARE STACK PRESENT? YES NO
IS FLARE ACTIVE? YES NO
IS GAS TO FLARE METERED? YES NO
AREA AROUND FLARE CLEARED? YES NO
ENVIRONMENTAL CONCERNS
IS VRU PRESENT? YES NO
IS VRU ACTIVE? YES NO
COMMENTS Compaster present con temp
Vapors
INSPECTOR Louis Colonson DATE 1-16-18