Submit 1 Copy To Appropriate District	State of New Me	exico		Form C-103	(
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-31930 5. Indicate Type of	Lagan	-
District III - (505) 334-6178	1220 South St. Fran	icis Dr.	STATE		1
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505 N 1 9 2018		6. State Oil & Gas		-
1220 S. St. Francis Dr., Santa Fe, NM		JANI			
87505	ICES AND DEDODTS ON WELLS	AFIVE	D	Lait A and and NI-	_
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BARE TO A			NEW MEXICO 'R'	Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		NEW WIEAICO K	STATE NCI-5	-	
PROPOSALS.)		8. Well Number	25	-	
1. Type of Well: Oil Well Gas Well Other   2. Name of Operator			9. OGRID Number 4323		-
CHEVRON U.S.A. INC.			9. OGRID Number	4323	
3. Address of Operator			10. Pool name or Wildcat		
6301 DEAUVILLE BLVD, MIDLAND, TX 79706			VACUUM DRINKARD		
4. Well Location					-
	1980 feet from the SOUT	TH line and	660 feet from th	e EAST line	
Section	1 Township 18-S	Range 34-		County LEA	-
Stellon	11. Elevation (Show whether DR,	0		County DEAT	
	3,984' (GL)	, 1010, 101, 010, 010./			
12. Check	Appropriate Box to Indicate N	ature of Notice.	Report or Other D	lata	
			•		
			SEQUENT REPORT OF:		
				PANDA 🛛	
	P&A NR - HVV.	CASING/CEMENT	I JOB		
	P&A R				
CLOSED-LOOP SYSTEM		OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAC				
proposed completion or red	completion.				
	<i></i>				
Final report and WBD for P&A operations attached Approved for Plugging of wellbore only. Liability					
			ding restoration ar		
			pecific for Subsequ		
Spud Date:   Report of Well Plugging, which may be found on the OCD web page under forms.					
Restoration Due By <u>01-22</u> -2019					
			•		
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief.		
SIGNATURE mit		· · ·		1/10/10	
SIGNATURE 740 4	IIILE_Produ	uction Engineer	DATE	1/18/18	
Type or print name _Michael Stewa	ert E-mail address: mi	ichael.stewart@chev	ron.com PHONE:	432-687-7431	
For State Use Only		ienaen.ste martiagene i			
h. 01	PIL D	ec		E 01/23/2018	
APPROVED BY:	tritale P.	E.S.	DATI	201/23/2018	
Conditions of Approval (if any):					

## NM R ST 3-25 – Workover Summary 12/21/17-1/17/18

- MIRU. TOOH w/ rods
- Tubing stuck, cut tubing @ 4,511', POOH w/ tubing
- Wash over damaged casing with air foam unit from 4541-4553'.
- RIH w/ OS to 4,550', POOH w/ fish.
- PU string mill and tag @ 4,527', cleanout to 4,587'
- Set 5.5" CIBP @ 7528', test to 500 psi, good test.
- Pump cement plug, Class C, 7,263-7,528' followed by plugging mud 6,315-7263', tag to verify.
- Pump cement plug 5,854-6,315'. Tag to verify.
- Test bad casing at 4541-4553', pressured up to 650 psi.
- Pump cement plug 4,480-4,604', tag to verify.
- Pump cement plug 3785-4018', tag to verify.
- Pump cement plug 2414-2727', tag to verify.
- Perforate casing at 1520', pump cement plug 1281-1562', tag to verify.
- Pump final plug 125' to surface. OL 17/18
- RDMO.

## FINAL WELLBORE DIAGRAM

