



FLARE INSPECTION

Batt is East + South of this well.

Deron

LEASE OR FACILITY NAME: *TAIPAN* *15-10 BS Cent. BATT.*

WELL # *TAIPAN* *10 ST. Com # 8H* API # 30- *025* - *42277*

U.L. *D* SEC *15* T *23s* R *33E*

FOOTAGE *240* (N) *1205* (S) E *1W*

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

COMMENTS: *Prod. gas going to sales*

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES ☐ NO

COMMENTS: *Has combustor on Tank vapors*

INSPECTOR *Ray Robinson* DATE *1-24-18*