

HOBBS OCD

JAN 23 2018

FLARE INSPECTION

RECEIVED

Merchison

LEASE OR FACILITY NAME Jackson

WELL # 24H API# 30- 025 - 41093

U.L. 0 SEC 22 T 24s R 33E

FOOTAGE 200 N/S 2435 ☒ E ☐ W

IS A FLARE STACK PRESENT?

☒ YES

☒ NO

IS FLARE ACTIVE?

☒ YES

☐ NO

IS GAS TO FLARE METERED?

☐ YES

☒ NO

AREA AROUND FLARE CLEARED?

☒ YES

☐ NO

ENVIRONMENTAL CONCERNS

Prod gas going to sales - Flare is
being used for tank vapors

IS VRU PRESENT?

☐ YES

☒ NO

IS VRU ACTIVE?

☐ YES

☐ NO

COMMENTS

INSPECTOR Gary Robinson DATE 1-23-18