

Taprock

HOBBS OCD

JAN 23 2018

# FLARE INSPECTION

Murchison

LEASE OR FACILITY NAME Jackson

WELL # 20-H API# 30-025 - 41139

U.L. D SEC 21 T 24s R 33E

FOOTAGE 200 N (S) 2290 (E) W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS Prod gas going to sales via comp.

Flare has had oil run over + small amount of  
oil @ bottom of flare on ground.

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS Tank vapors going to combustor

INSPECTOR Gary Robinson DATE 1-23-18