FLARE INSPECTION

HOBBS OCD
JAN 2 3 2018
RECEDITED

Murchison				KECEIVED
LEASE OR FACILITY	VAME JACK	SN		
WELL # 12H	API# 3	0-025	41227	
U.L. A SEC 16	T 24	5 R	33c	
FOOTAGE 200	<u> </u>	960	(E)/W	
IS A FLARE STACK PR	ESENT?	1ES	NO	
IS FLARE ACTIVE?	,	YES	NO	
IS GAS TO FLARE ME	TERED?	(ES)	NO	
AREA AROUND FLAR	1	YES	NO	
ENVIRONMENTAL CO	NCERNS Tool	gas	roing to Sa	les
IS VRU PRESENT?		YES	(NO)	
IS VRU ACTIVE?		YES	NO	
COMMENTS				
Compuster used o	on temp vo	pars		
INSPECTOR Man	Robinson	DATE_	1-23-18	
U				