

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

Merchison

LEASE OR FACILITY NAME JACKSON

WELL # 23H API# 30- 025 - 41229

U.L. N SEC 22 T 24S R 33E

FOOTAGE 200 N / (S) 1670 E / (W)

IS A FLARE STACK PRESENT? (YES) NO

IS FLARE ACTIVE? YES (NO)

IS GAS TO FLARE METERED? YES (NO)

AREA AROUND FLARE CLEARED? (YES) NO

ENVIRONMENTAL CONCERNS Prod gas going to sales - Flare
is being used for tank vapors

IS VRU PRESENT? YES (NO)

IS VRU ACTIVE? YES NO

COMMENTS

INSPECTOR Gary Robinson DATE ~~1-23-18~~ 1-23-18