

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

Murchison

LEASE OR FACILITY NAME Bettis 20 ST com

WELL # 4H API# 30-025 - 41438

U.L. N SEC 20 T 24s R 33e

FOOTAGE 200 N / S 1670 E / W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS Prod gas going to sales via
compressor

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS Combuster being used on tank vapors

INSPECTOR Gary Robinson DATE 1-23-18