

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

Murchison

LEASE OR FACILITY NAME *Bettis 20 ST Com*

WELL # *#5H* API# 30- *025* - *41439*

U.L. *M* SEC *20* T *24s* R *33e*

FOOTAGE *200* N *(S)* *380* E *(W)*

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? ☐ YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

ENVIRONMENTAL CONCERNS *Liquid gas going to sales via
Compressor*

IS VRU PRESENT? ☐ YES ☒ NO

IS VRU ACTIVE? ☐ YES ☐ NO

COMMENTS *Combuster being used on Tank vapors*

INSPECTOR *Gary Robinson* DATE *1-23-18*