Form 3160-4

UNITED STATES DEPARTMENT OF THE INTERIOR

HOBBS OCDORM APPROVED (August 2007) Expires: July 31, 2010 BUREAU OF LAND MANAGEMENT WELL COMPLETION OR RECOMPLETION REPORT AND LOCKED NMNM118723 If Indian, Allottee or Tribe Name 1a. Type of Well Oil Well ☐ Gas Well □ Dry Other b. Type of Completion New Well ☐ Work Over □ Deepen Plug Back Diff. Resvr. 7. Unit or CA Agreement Name and No. Other Name of Operator
 CHEVRON USA INC Contact: DENISE PINKERTON Lease Name and Well No. SD WE 23 FED P25 001# 5H E-Mail: leakejd@chevron.com 9. API Well No. 1616 W. BENDER BLVD 3a. Phone No. (include area code) Ph: 432-687-7375 3. Address 30-025-43460-00-S1 HOBBS, NM 88240 4. Location of Well (Report location clearly and in accordance with Federal requirements)*
Sec 23 T26S R32E Mer NMP 10. Field and Pool, or Exploratory **JENNINGS** At surface SESW 260FSL 2603FWL 32.021484 N Lat, 103.645325 W Lon 11. Sec., T., R., M., or Block and Survey or Area Sec 23 T26S R32E Mer NMP Sec 14 T26S R32E Mer NMP NENW 330FSL 1670FWL 32.039600 N Lat, 103.893570 W Lon At top prod interval reported below NENW 33 Sec 14 T26S R32E Mer NMP 12. County or Parish 13. State NENW 180FNL 1815FWL 32.049667 N Lat, 103.648277 W Lon LEA NM At total depth 14. Date Spudded 01/24/2017 15. Date T.D. Reached 17. Elevations (DF, KB, RT, GL)* 16. Date Completed 04/08/2017 3121 GL 18. Total Depth: MD 19196 19. Plug Back T.D.: MD 19136 MD 20. Depth Bridge Plug Set: TVD 9025 TVD TVD No No No No 21. Type Electric & Other Mechanical Logs Run (Submit copy of each) CBL Was well cored? Yes (Submit analysis) Was DST run? Yes (Submit analysis) Directional Survey? Yes (Submit analysis) 23. Casing and Liner Record (Report all strings set in well) Bottom Stage Cementer No. of Sks. & Slurry Vol. Size/Grade Wt. (#/ft.) Cement Top* Amount Pulled Hole Size (MD) (MD) Depth Type of Cement (BBL) 17.500 13.375 J-55 54.5 0 920 0 742 0 0 12.250 9.625 HCK-55 40.0 4591 1511 8.750 5.500 HCP-110 20.0 0 19186 2641 2250 24. Tubing Record Depth Set (MD) Packer Depth (MD) Size Depth Set (MD) Packer Depth (MD) Size Depth Set (MD) Packer Depth (MD) 8619 8600 25. Producing Intervals 26. Perforation Record Top Bottom Size No. Holes Formation Perforated Interval Perf. Status BONE) SPRINGS UPPER SHAL PRODUCING (SEE DETAILED PER 9228 TO 19004 B) **BONE SPRING** 9228 19004 C) D) 27. Acid, Fracture, Treatment, Cement Squeeze, Etc. Depth Interval Amount and Type of Material 9228 TO 19004 TOTAL PROPPANT: 15,710,286 LBS (SEE DETAILED FRAC SUMMARY ATTACHED ZU)0 28. Production - Interval A Date First Test Oil Gravity Hours Test Water Gas BBL MCF BBL BUREAU OF LAND MANAGEMENT Corr. API Gravity 07/01/2017 08/06/2017 CARWSETROPHWEDLOFFICE Choke Tbg. Press Csg. 24 Hr Oil Gas Water Gas-Oil Well Status MCF 849 Press Rate BBL BBL Size Flwg. Ratio 48/64 SI 490.0 391 673 1218 1721 POW 28a. Production - Interval B Oil Gravity Gas MCF Date First Test Hours Test Water Gas Production Method Corr. API Production BBL BBL Gravity Date Tested Produced 07/01/2017 08/06/2017 24 FLOWS FROM WELL

490.0 (See Instructions and spaces for additional data on reverse side)

Csg.

849 Press

24 Hr

Rate

Choke

48/64

Size

Tbg. Press

Flwg.

ELECTRONIC SUBMISSION #384103 VERIFIED BY THE BLM WELL INFORMATION SYSTEM

MCF

673

BBI

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

BBI

1218

Gas:Oil

1721

Ratio

Well Status

POW

Reclamation due 12/10/2017

28b. Produ	ction - Interva	al C											
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API		Gas Gravit		Production Method		
rioduced	Date	Testeu	- Codection	BBL	Wici	BBL	Coll. Al I		Giavit	y			
Choke Size	Tbg. Press. Flwg.			Gas MCF				Well Status					
Size	SI	11033.		DDL	MCI	DDL	Ratio						
	ction - Interva	l D											
Date First Produced			Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API		Gas Gravity		Production Method		
Choke Size				Oil BBL	Gas MCF	Water BBL	Gas:Oil Ratio		Well Status		3		
29. Disposi	29. Disposition of Gas(Sold, used for fuel, vented, etc.) SOLD												
	ry of Porous	Zones (I	nclude Aquife	rs):						31. For	mation (Log) Markers		
tests, in	all important z acluding depth overies.	ones of interva	porosity and co l tested, cushio	on used, time	eof: Cored in e tool open,	ntervals and flowing and	all drill-ster	m ssures					
Formation			Тор	Bottom		Descriptions, Contents, etc.					Name	Top Meas. Depth	
CASTILE LAMAR LS BELL CAN' CHERRY C BONE SPR AVALON	YON CANYON CANYON RING LIME	include	2855 4505 4540 5550 7123 8818 8882	4504 4539 5549 7122 8817 8881 19196	LIM SAN SAN SAN	HYDRITE IESTONE NDSTONE NDSTONE NDSTONE ALE/LIMES				LAI BE CH BR BO	STILE MAR LS LL CANYON ERRY CANYON USHY CANYON NE SPRING LIME ALON	2855 4505 4540 5550 7123 8818 8882	
22 Circle 6	enclosed attac	hments											
Circle enclosed attachments: Electrical/Mechanical Logs (1 full set req'd.) Geologic Report								DST Report 4. Directional Survey					
5. Sundry Notice for plugging and cement verification 6. Core Analysis 7 Other:											Survey		
34. I hereby	y certify that t	the foreg	going and attac	hed informa	tion is comp	plete and con	rrect as dete	rmined fro	om all	available	records (see attached instruction	ons):	
			Electr	onic Submi			d by the BL			ation Sy	stem.		
		(Committed to							2/2017 (1	7DW0072SE)		
Name (please print) DENISE PINKERTON Title PERMITTING SPECIALIST													
Signature (Electronic Submission)						Date <u>08/08/201</u>							
Title 18 U.S	S.C. Section 1	001 and	Title 43 U.S.O	C. Section 1:	212, make it	t a crime for	any person	knowingl	y and	willfully	to make to any department or a	agency	

Revisions to Operator-Submitted EC Data for Well Completion #384103

Operator Submitted

BLM Revised (AFMSS)

Lease:

NMNM118723

NMNM118723

Agreement:

Operator:

CHEVRON U.S.A. INC. 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432-687-7375

CHEVRON USA INC 1616 W. BENDER BLVD HOBBS, NM 88240 Ph: 575-263-0431

Admin Contact:

DENISE PINKERTON PERMITTING SPECIALIST E-Mail: leakejd@chevron.com DENISE PINKERTON PERMITTING SPECIALIST E-Mail: leakejd@chevron.com

Ph: 432-687-7375

Ph: 432-687-7375

Tech Contact:

DENISE PINKERTON PERMITTING SPECIALIST E-Mail: leakejd@chevron.com DENISE PINKERTON PERMITTING SPECIALIST E-Mail: leakejd@chevron.com

Ph: 432-687-7375

Ph: 432-687-7375

Well Name: Number: SDWE 23 FED P25

SD WE 23 FED P25

001H

Location:

State:

NM

County: S/T/R:

LEA

Sec 23 T26S R32E Mer NMP 260FSL 2603FWL

Surf Loc:

Field/Pool:

JENNINGS; UPR BN SPR SHALE

Logs Run:

CBL

UPPER BONE SPRING, SHALE

NM

LEA Sec 23 T26S R32E Mer NMP

SESW 260FSL 2603FWL 32.021484 N Lat, 103.645325 W Lon

JENNINGS

CASTILE

CBL

Producing Intervals - Formations:

BONE SPRINGS UPPER SHAL

BONE SPRING

Porous Zones:

CASTILE LAMAR BELL CANYON CHERRY CANYON BRUSHY CANYON BONE SPRING LIME UPPER AVALON

LAMAR LS BELL CANYON CHERRY CANYON BRUSHY CANYON BONE SPRING LIME **AVALON**

Markers:

CASTILE LAMAR **BELL CANYON** CHERRY CANYON BRUSHY CANYON BONE SPRING LIME **UPPER AVALON**

CASTILE LAMAR LS BELL CANYON CHERRY CANYON BRUSHY CANYON BONE SPRING LIME

AVALON