

FEB 07 2018

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron		API Number 30-025-34788 ✓	
Property Name NM EA ST		Well No. 1 ✓	

⁷ Surface Location

UL - Lot A	Section 24	Township 18s	Range 37E	Feet from 410	N/S Line N	Feet From 610	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	<input type="radio"/> NO	SHUT-IN YES	<input type="radio"/> NO	INJECTOR INJ	SWD	<input type="radio"/> OIL	PRODUCER GAS	DATE 2-7-18
------------------	--------------------------	----------------	--------------------------	-----------------	-----	---------------------------	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	10	N/A	20	125
Flow Characteristics					
Pull	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/N	Y/N	CO2 ___
Steady Flow	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/N	Y/N	WTR ___
Surges	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/N	Y/N	GAS ___
Down to nothing	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/N	Y/N	Injected for
Water	Y/ <input type="radio"/> N	Y/ <input type="radio"/> N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

INT-CSS 10PSI to zero in 3min ✓

Signature: Braxton Baty	OIL CONSERVATION DIVISION
Printed name: Braxton Baty	Entered into RBDMS
Title:	Re-test JK
E-mail Address:	
Date:	
Phone:	
Witness: Gary Robinson 505-399-3220	