



## FLARE INSPECTION

COG

LEASE OR FACILITY NAME: Wild Cobra 1 ST

WELL # 2H API # 30-025 - 40404

U.L. E SEC 1 T 19s R 34e

FOOTAGE 1815 ☒ NYS 460 E ☒ W

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

COMMENTS: Prod. gas going to sales

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES ☐ NO

COMMENTS: Tank vapors are vented

INSPECTOR Gary Colson DATE 2-8-18