



FLARE INSPECTION

Devon

LEASE OR FACILITY NAME: ~~Playa~~ Playa 2 ST.

WELL # 1H API # 30- 025 - 40405

U.L. N SEC 2 T 19s R 34E

FOOTAGE 330 N/S 2190 E / (W)

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? ☐ YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

COMMENTS: Prod. gas going to sales

IS VRU PRESENT? ☒ YES ☐ NO

IS VRU ACTIVE? ☒ YES ☐ NO

COMMENTS: Has combustor in addition to vruc on tank vapors

INSPECTOR Gary Robinson DATE 2-9-18