UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


5. Lease Serial No.

NMLC031740B

Do not use thi abandoned wel	6. If	6. If Indian, Allottee or Tribe Name			
SUBMIT IN 1	7. If	Unit or CA/Agree	ment, Name and/or No.		
Type of Well		8. Well Name and No. EUNICE MONUMENT SOUTH UNIT 262H			
Name of Operator XTO ENERGY, INC		PI Well No. 0-025-04454	/		
3a. Address 500 W. ILLINOIS ST STE 100 MIDLAND, TX 79701	3b. Ph	. Phone No. (include area code) n: 432-620-6714		Field and Pool or E UNICE MONUI	xploratory Area MENT; GB-SA
4. Location of Well (Footage, Sec., T.	11.	County or Parish, S	State		
Sec 3 T21S R36E Mer NMP 6	L	LEA COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, REP	ORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent ■ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (S	tart/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation		☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete		☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	▼ Temporarily .	Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Dispos		
following completion of the involved testing has been completed. Final At determined that the site is ready for fix XTO Energy, Inc respectfully referenced well using the follo 1. Set CIBP @ 3455? 2. Cap w/25sx cmt thru tbg or 3. WOC 4 hours. Tag. 4. Run good MIT. A closed-loop system will be used.	requests a 5 Year Temporary wing procedure: 35? via wireline	Abandon based on econo		CHED FOI	R
14. I hereby certify that the foregoing is	s true and correct.	/			1. /1
	Electronic Submission #4017 For XTO EN	ERGY, INC, sent to the Hol	bbs		
	Committed to AFMSS for pro	ocessing by PRISCILLA PE	REZ on 02/01/2018	3 / /	/ //
Name (Printed/Typed) STEPHAN	NIE RABADUE	Title REGUL	ATORY ANALYS	ST /	
Signature (Electronic S	Submission)	Date 01/22/20	APP	ROYED	
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		M
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conductive to conduct the conductive that the applicant to conduct	uitable title to those rights in the sub		BUREAU OF A	AND MANAGEM D FILL OFFICE	Date
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crim	ne for any person knowingly and			
	statements of representations as to al	ny matter within its jurispiction			#
(Instructions on page 2) ** OPERA	TOR-SUBMITTED ** OPE	RATOR-SUBMITTED *	* OPERATOR-	SUBMITTED	**


MUB/OCD 3/1/2018

EUNICE MONUMENT SO. UNIT #262H SHL: 661' FSL & 663' FWL BHL: 3080' FSL & 2160' FEL SEC 3, T215, R36E LEA CO, NM AP# 30-025-04454 CURRUH WBD



EUNICE MONUMENT SO. UNIT #262H
SHL: 661' FSL & 663' FWL
BHL: 3080' FSL & 2160' FEL
SEC 3, T21S, R36E
LEA CO, NM
API# 30-025-04454

proposed WBD



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 1 year ending 02/22/2019 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands
Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with wellbore diagram
 with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Eunice Monument South Unit 262H

- 1. Well is approved to be TA/SI for a period of 1 year or until 02/22/2019
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 02/22/2019
- 3. COA's met at this time.