## State of New Mexico

MAR 0 2 2018

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office RRADENHEAD TEST REPORT

RECEIVED

				BRADENH	EAD TES	T REPO	RT					
Operator Name Cross Timber Energy, LLC								3 API Number 3002524600				
Property Name								Well No.				
North Vacuum ABO East Unit								1				
				2. Surfa	ace Location	1						
UL - Lot			Range 35E	The state of the s				Feet From 1980	E/W Line FEL	County		
				We	ell Status							
Well	Status		SHUT-IN		PRODUCING		2-28-1		1	<u> </u>		
				RMEDIATE TO A	ATMOSPHER							
11 bradenhead	flowed was		(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Intern Prod		Prod Csng	(E)Tubing		
Pressure		IAI					(C)Interm-Prod		O			
Flow Characteristics			0	0						4150		
Puff		, ·	10	Y / 🗞		Y / N			Ø/ N	-		
Steady Flow			10	Y / O		Y / N			V / Ø			
Surges			10	Y / 6			Y / N		Y / 🛇			
Down to nothing		6	Ø / N		Ø / N		Y / N		Ø N			
Gas or Oil		Y	Y / 6 Y			Y / N			Y /0			
Water		١	10	Y / 6	3	Y / N			Y / 🛇			
If bradenhead	flowed wat	er, check all	of the description	is that apply:								
	CLEAR		SH SH	SALTY			SULFUR		BLACK			
						Joe Li on						
Remarks:					ī	NJECTING A	AT THIS	TIME 1	WTR,	GAS,CO2		
		7	1									
Signature	Signature / L								OIL CONSERVATION DIVISION			
Printed name	Printed name James Embrul							Entered into RBDMS				
Title. Lease Operator							Re-test					
E-mail Addres	ss: ten	bree 6	9 ctfbel	dsvcs.com	~				KA			
Date 2-2	28-18		Phone (57)	5) 70422 Kery Tu	41							
			Witness	Kerry To	tru-	- OCD						

399-3221