Submit One Copy To Appropriate District Office State of New Mex	
District I Energy, Minerals and Natura	al Resources Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II OLL CONSERVATION I	
District II 811 S. First St., Artesia, NM 88210 District III District III 1220 South St. France	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	MANTED
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	G.B.C.COA E W WALDEN
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJ	8. Well Number 12
2. Name of Operator	9. OGRID Number
CHEVRON USA INC	4323
3. Address of Operator	10. Pool name or Wildcat
6301 DEAUVILLE BLVD, MIDLAND TX 79706	PENROSE;SKELLY GB/EUNICE SW SA
4. Well Location	
Unit Letter F: 2250 feet from the NORTH line and 1350 feet from the WEST line	
Section 15 Township 22S Range 37 E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐	
	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the Underground marker 4 '	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
☐ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
****Landowner requested caliche be left piled up for his personal use.Road and location ripped up and reseeded per	
Landowner*** When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE	
TYPE OR PRINT NAME <u>CINDY HERRERA-MURILLO</u> EMAIL: <u>EEOF@CHEVRON.COM</u> PHONE: <u>575-263-0431</u>	
For State Use Only	
APPROVED BY: Mark Whiteham TITLE P.E.S. DATE 03/22/2018	
Conditions of Approval (if any):	