| District I – (575) 393-6161 Energy, Minerals and Natural Resources Revised July 18, WELL API NO. 30-025-12286 | 013 |
|--|-------------|
| District II (575) 748 1283 | |
| | |
| Indicate Type of Lease | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505 6. State Oil & Gas Lease No. | - |
| 1220 S. St. Francis Dr., Santa Fe, NM | |
| SUNDRY NOTICES AND REPORTS ON WILLS 7. Lease Name or Unit Agreement Name of Unit Agreement | e |
| SUNDRY NOTICES AND REPORTS ON WIRDS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SOCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 7. Lease Name or Unit Agreement Name of Unit Agreement Na | |
| PROPOSALS.) 8 Well Number 64 | |
| 1. Type of Well: Oil Well ☐ Gas Well ☒ Other 2. Name of Operator 9. OGRID Number 4323 | _ |
| Chevron USA INC | |
| 3. Address of Operator 6301 DEAUVILLE BLVD., MIDLAND, TX 79706 10. Pool name or Wildcat Shoe Bar, Strawn NE | |
| 4. Well Location | |
| Unit Letter1: 998feet from theSouth line and660feet from theEast line | |
| Section 31 Township 24S Range 38E NMPM County Lea | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) | |
| 3,122' GL | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | |
| Approved for Blugging of wellbore only Liability 3SEQUENT REPORT OF: | |
| Approved for Fideging of Weiner control of the Casing Casing | |
| completion of the C-103, Specific for Subsequent | \boxtimes |
| Report of Well Plugging, which may be found on I POLATINE WIJOB | |
| the OCD web page under forms. P&A R Restoration Due By 03-20-2019 | |
| | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimate | date |
| of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | |
| 03/15/18 MIRU, Apollo slickline PU 1.40 gauge ring with lubricator test to 1000 psi held good. Rih & tagged up @ 6290'. POOH | |
| gauge ring, pick up 1.23 prong RIH & tagged up @6305' below pkr. POOH. PU 1.50 gauge ring, RIH & tag @ 6289'. POOH. RIH | vith |
| 1.50 plug. Set plug try to shear off plug slipped out. POOH still had plug. 03/16/18 Set 1.5 F plug in profile @ 6290'. Test casing to 560 psi – good. NU BOP. Released on/off tool. Mixed 20 sx Cl C cmt, | cet |
| cmt plug fr 6289'-5887'. LD 18 jts 2-3/8" tbg, pull 30 more jts, left 147 in hole, EOT @ 4732'. SDNF | sei |
| 03/17/18 Tag TOC @ 5869', tstd csg to 700 psi held good. Ran CBL f/ 5856' t/ surface - good bond f/ 5856' t/ 3150', spotty bond | |
| 3150' t/ 2500', good bond f/ 2500' t/ 1950', spotty bond f/ 1950' t/ 1250', good bond f/ 1250' t/ surface. Mixed 20 sx Cl C cmt, set | lug |
| fr 5154'-4753', no need to tag. Mixed 35 sx Cl C cmt, set plug fr 4011'-3308'. LD 32 jts, EOT @ 2961'. TOC @ 3308'. SDFN 03/19/18 TIH, tag TOC @ 3611', discussed w/MW-OCS. Spot 20 sx Cl C cmt fr 3611'. Mixed 20 sx Cl C cmt fr 3611'-3210'. LD | 2 its |
| 2-3/8", EOT @ 2897'. TIH & tag TOC @ 3158'. LD 13 jts 3-3/8", EOT @ 2702'. Mixed 20 sx Cl C cmt. LD 22 jts, EOT @ 1992'. | _ , |
| SDFN | C |
| 03/20/18 TIH tag TOC @ 2240'. Mixed 20 sx Cl C cmt fr 1300'-900'. Perf @ 370' (no injection rate) & again @ 200' (injection ra 1.5 bpm @ 700 psi. Circ out 13-3/8". Closed surface. Mixed & spot 11 sx Cl C cmt fr 422'-200'. Mixed 130 sx Cl C cmt to surface | 10 9 |
| down 4" out 13-3/8". Turn over to reclamation. | |
| | |
| | |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | |
| 3/26/2018 | |
| | |
| X Nick Glann | |
| Nick Glann | |
| Nick Glann | |
| Well Abandonment Engineer | |
| SIGNATURE Signed by: Nick Glann E-mail address: <u>nglann@chevron.com</u> PHONE: <u>432-687-7786</u> | |
| APPROVED BY: DATE 03/27/20 | 8 |