Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources	Form C-103 October 25, 2007
1625 N. French Dr., Hobbs, NM 87240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III District II District III District III	WELL API NO. <u>30-025-36010</u> 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	STATE X FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 27816
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name:
	8. Well Number
1. Type of Well: X Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number
Energen Resources Corporation	162928
3. Address of Operator	10. Pool name or Wildcat
3510 N. "A" St., Bldgs A & B, Midland, TX 79705 4. Well Location	Saunders, San Andres
Unit Letter <u>N</u> : <u>990</u> feet from the <u>South</u> line and <u>1650</u> feet from the <u>West</u> line	
Section 4 Township 15S Range 33-E NMPM	County Lea, New Mexico
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4206' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE D	RILLING OPNS. P AND A
PULL OR ALTER CASING	ENT JOB
OTHER:	is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	production equipment and Junk have been removed
All metal bolts and other materials have been removed. Portable bases have been	n removed. (Poured onsite concrete bases do not have
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
	a schedule an inspection. If more than one
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
Brand, ERothien 14 articles Re. Analyst 432-688-3323 19118	
SIGNATURE Tammy Gask TITLE Assistant Production Superintendent DATE 1-9-18	
TYPE OR PRINT NAME Tommy York E-MAIL tommy.york@energen.com PHONE 432-209-2483	
APPROVED BY Mach Whitelen TITLE PIE.S. DATE 04/03/2018	
APPROVED BY COMPANY TITLE TITLE DATE DATE DATE	