

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
APR 03 2018
RECEIVED

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 3002503770
Property Name LOVINGTON PADDOCK UNIT	Well No. 42

7. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
m	30	10S	30E		1060	S	990	W	LEA

Well Status			
Well Status	SHUT-IN	PRODUCING	DATE 3-14-18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1800
<u>Flow Characteristics</u>					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2
----------	--

Signature: 	OIL CONSERVATION DIVISION
Printed name: Mark FSA	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: MARKF@Chevron.com	
Date: 3-14-18	
Phone: 432 955 4967	
Witness: Dany Holmson	