Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter

NMNM128366

abandoned we	II. Use form 3160-3 (AP	D) for such propos	sals.	06 2018	6. If Indian, Allottee or	r Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2				90	7 If Unit or CA/Agree NMNM70976X	ment, Name and/or No.
Type of Well			RE	CEI	8. Well Name and No. LEA UNIT 50H	
Name of Operator					9. API Well No. 30-025-44411	
3a. Address 303 W WALL, STE 1800 MIDLAND, TX 79702 3b. Phone Ph: 432			(include area code) 1-6339		10. Field and Pool or Exploratory Area LEA/BONE SPRING	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, S	State
Sec 1 T20S R34E SWSE 630FSL 2560FEL			LEA COUNTY, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	Deepen		☐ Product	ion (Start/Resume)	■ Water Shut-Off
	Alter Casing		☐ Hydraulic Fracturing		ation	☐ Well Integrity
Subsequent Report	☐ Casing Repair ☐ New Constru			Recomplete		Other Drilling Operations
☐ Final Abandonment Notice	☐ Change Plans				rarily Abandon	
	☐ Convert to Injection ☐ Plug				Osposal roposed work and approximate duration thereof.	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Please find attached the Drilling Operations Summary: 14. Thereby certify that the foregoing is true and correct. Electronic Submission #409511 verified by the BLM Well Information System						
Name (Printed/Typed) MATT DICKSON Reserves operating LP, sent to the Hobbs Committed to AFMSS for processing by JENNIFER SANOHEZ on 03/29/2018 TO RECOMMENDED Name (Printed/Typed) MATT DICKSON Title DRILLING ENGINEER IN RECOMMENDED Title DRILLING ENGINEER IN RECOMMENDED TO SENT TO						
Signature (Electronic S	Submission)	Date	03/28/20	18 /д	PR 2018/	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By		Title		BUKEAU	OF VAND MANAGEME SBAD FIELD OFFICE	Date
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title CARLSBACTELU UPTET Date Office						
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						
(Instructions on page 2)						

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Lea Unit #50H - Sundry Notice

Subsequent Report

*Other

Drilling Operations

02-Mar-2018: Spud well @ 22:00 hours.

03-Mar-2018: Drilled 17-1/2" hole to 1,800' MD (TD). Ran 44 joints of 13-3/8", 54.5#, J-55, STC casing set @ 1,795'. Pumped lead cement: 1,300 sx of P/H 50:50, 11.90 ppg, 2.47 yield, followed by tail cement: 1600 sx PVL, 12.60 ppg, 1.62 yield. Circulated 454 sx / 200 bbls of cement to surface.

04-Mar-2018: WOC 8 hours. Installed Cameron 13-5/8" x 3K wellhead and test to 500 psi (good). Installed 13-5/8" x 5K mud cross, double-ram preventer and annular preventer, rotating head bowl and flow nipple. Test BOP, top-drive, floor valves and mud lines to 3000 psi high / 250 psi low. Tested annular preventer to 2500 psi, and tested 13-3/8" surface casing to 1000 psi (good).

06-Mar-2018: Drilled 12-1/4" intermediate hole to a TD of 5,58Q'.

07-Mar-2018: Ran 45 joints of 9-5/8" 47#, HCL-80, LTC casing and 84 joints of 9-5/8" 40#, J-55, LTC casing set @ 5,570'. Pumped first stage lead cement: 1700 sx of 35:65 Poz/Class C, 12.60 ppg, 1.94 yield followed by first stage tail cement: 350 sx of Class H, 15.6 ppg, 1.18 yield. Opened DV Tool @ 1,883' and pumped second stage lead cement: 700 sx of Class C Neat, 14.80 ppg, 1.32 yield. Circulated 165 sx / 39 bbls of cement to surface. WOC 8 hours. Installed B Section and tested to 1800 PSI. Installed 13-5/8" x 5K Double Ram Preventer and 5K annular. Tested BOPE, choke manifold and all valves to 5000 psi high / 250 psi low. Tested 9-5/8" casing to 1500 psi (all test good).

19-Mar-2018: TD 8-1/2" production hole @ 15,020' MD / 9,517' TVD.

20-Mar-2018: Ran 345 joints of 5-1/2" 20#, HCP-110, GBCD casing set @ 15,018' MD. Pumped first stage lead cement: 1300 sx P/H 50:50, 11.9 ppg, 2.47 yield followed by tail cement: 1600 sx PVL, 12.6 ppg, 1.62 yield. Circulated 386 sx / 170 bbls of cement to surface. Set 5-1/2" casing slips and install 7-1/16" x 10k tubing spool, and test to 3800 psi (good).

21-Mar-2018: Rig release @ 22:00 hours. End of drilling operations, preparing well and location for completion operations.

Matt Dickson
Drilling Engineer
(432) 689-5204
mdickson@legacylp.com