<u>trict II</u> S. First St., I <u>rict III</u> 0 Rio Brazo I <u>rict IV</u> 0 S. St. Fran	h Dr., Hobbs, NM 88240 , Artesia, NM 88210 os Road, Aztec, NM 87410 Incis Dr., Santa Fe, NM 87505 APR 2 6 2018 APR 2 6		
(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)			
A.	Applicant,		
	whose address is6301 Deauville Blvd., Midland, TX 79706,		
	hereby requests an exception to Rule 19.15.18.12 for90days or until, Yr, for the following described tank battery (or LACT):		
	Name of Lease <u>Brininstool Tank Battery</u> Name of Pool <u>Bell Lake, Bone Spring North</u>		
	Location of Battery: Unit LetterSection 23 Township 23S Range 33E		
	Number of wells producing into battery Four – see below		
B.	Based upon oil production of <u>~ 379</u> barrels per day, the estimated * volume		
	of gas to be flared is MCF; Value per day.		
C.	Name and location of nearest gas gathering facility: <u>Targa Gas Gathering</u>		
D.	Distance 25 miles Estimated cost of connection Unknown		
E.	This exception is requested for the following reasons:		
sales	Purchaser sales line has intermittent high pressure, not allowing gas from the battery to flow through the gasline.Brininstool 23 23 33 #1H; Brininstool 23 23 33 #2H; Brininstool 25 23 33 #2H;instool 24 23 33 #2HAPI #s – 30-025-41330; 30-025-41331; 30-025-40627; 30-025-41935		

OPERATOR	OIL CONSERVATION DIVISION
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.	Approved Until7/19/2018
	By Mapy Brown
Signature CirilyHanne-Murillo	Title AO /II
Printed Name& Title: <u>Cindy Herrera-Murillo</u> , <u>Permitting Specialist</u>	Date 5/2/2018
E-mail Address <u>eeof@chevron.com</u>	
Date 04/19/2018 Telephone No. 575-263-0431	

=

* Gas-Oil ratio test may be required to verify estimated gas volume.