Submit One Copy To Appropriate District State of New Mex	vico	Form C-103
Office HOBBS OCD Viscous Land Natural Processing		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 811 S. First St., Artesia, NM 88210 MAY 15 2018 CONSERVATION DIVISION		30-025-36454
District III 1000 Rio Brazos Rd., Aztec, NM 87 RECEIVED 1220 South St. Francis Dr. Santa Fe, NM 87505		5. Indicate Type of Lease STATE FEE
		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)		BIG JAKE
1. Type of Well: Oil Well Gas Well Other		8. Well Number 1
Name of Operator DEVON ENERGY PRODUCTION CO LP		9. OGRID Number 6137
3. Address of Operator		10. Pool name or Wildcat
PO BOX 250, ARTESIA, NM 88211		OSUDO; MORROW, WEST (GAS)
4. Well Location		
Unit Letter P: 1000 feet from the SOUTH line and 660 feet from the EAST line		
Section 34 Township 20S Range 35E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3725.5' KB; 3697' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORLD		
TEMPORARILY ABANDON		
TOLE ON ALTER GASING		
OTHER:		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Lenuse menoud TITLE ADMIN FIELD SUPPORTDATE5/15/2018		
TYPE OR PRINT NAME Denise Menoud E-MAIL: <u>denise.menoud@dvn.com</u> PHONE: 575-746-5544		
For State Lice Only		
APPROVED BY: Mach Whitsher TITLE P. E.S. DATE 05/22/2018		
Conditions of Approval (if any):	12.0	DATE OSTECTION