State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

HOBBS OCD

BRADENHEAD TEST REPORT

PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating								30-025-10533			
Property Name SKELLY PENROSE B UNIT								Well No.			
				7. Surface Locat	ion						
UL - Lot Section 31		rnship Range 2S 37E		Feet from 1980		N/S Line Fee SOUTH			W Line AST	County LEA	
,				Well Status	5			•			
Ta' D Well No		shut-in No		INJECTOR		PRODUCING Oil			05/31/2018		
		ADENHEAD AND IN		OBSERVED DA		VIDUALL	Y FOR 15 MIN	UTES EA	СН		
ii bradeinieau nowed water, c		(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure		<u>0#</u>						38		38	
Flow Characteristic	<u>es</u>		+		+						
Puff		N	Y / N		Y / N			Y / N		-	
Steady Flow		N	Y / N		Y / N			Y - N		-	
Surges		N	Y / N		Y / N			Y - N		-	
Down to nothing		Y	Y / N		Y / N			Y / N			
Gas or Oil		N	Y / N		Y / N			Y / N			
Water		N	Y / N		Y / N			Y / N			
f bradenhead flowed water, o		FRESH		SALTY		SULFUR		BLACK			
Remarks:											
C. Durky							OIL CONSERVATION DIVISION				
Signature											
Printed name: C. DALE KELTON							Entered into RBDMS				
Title: PRESIDENT							Re-test		7.6		
E-mail Address: providenceenergy@suddenlink.net								/	M	/	
Date: 06/04/2018	Phone: 432	Phone: 432-661-1364									

Witness: