

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-34757
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Stingray 10 State
8. Well Number 1
9. OGRID Number 229137
10. Pool name or Wildcat Wildcat - Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

COG Operating, LLC

3. Address of Operator

600 W. Illinois Ave, Midland, TX 79701

4. Well Location

Unit Letter **J** : **2000** feet from the **S** line and **2000** feet from the **E** line
Section **10** Township **17S** Range **33E** NMPM County **LEA**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4152' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF IN

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

DOWNHOLE COMMINGLE ☐

CLOSED-LOOP SYSTEM ☐

OTHER: ☐

INT TO PA

P&A NR **Pm**

P&A R

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING/CEMENT JOB ☐

ALTERING CASING ☐

P AND A ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/11/18 MIRU Plugging equipment. Dug out cellar, ND well head, NU BOP. 05/14/18 RIH w/ guage ring & junk basket to 10360', could not get through. Notified Mark Whitaker w/ NM OCD. Set 5 1/2" CIBP @ 10360'. Tagged CIBP @ 10360'. Circulated hole w/ MLF. Pressure tested csg, csg did not hold. 05/15/18 Spotted 25 sx class H cmt @ 10360-10107'. (Notified Mark Whitaker w/ NMOC & WOC.) Tagged plug @ 10120'. Perf'd csg @ 7815'. Sqz'd 50 sx class H cmt @ 7815-7960'. WOC. 05/16/18 Tagged plug @ 7960'. 0 psi on 5 1/2" csg. Perf'd @ 6070'. RIH to 6120'. Spotted 100 sx class C cmt to 5109'. WOC. Tagged plug @ 5300'. ND BOP. RU casing jacks & spear, worked on 5 1/2" csg to get free. Rigged down spear & csg jacks. NU BOP. 05/17/18 RIH w/ wireline & csg cutter. Cut 5 1/2" csg @ 4646', worked csg free. POH w/ 110 jts 5 1/2" csg. 05/18/18 Spotted 80 sx class C cmt @ 4733-4433'. WOC. Tagged plug @ 4430'. Spotted 55 sx class C cmt @ 2200-2033'. WOC. 05/21/18 Tagged plug @ 2065'. Spotted 55 sx class C cmt @ 1750-1583'. WOC. Tagged plug @ 1645'. Perf'd 9 5/8" csg @ 495', pressured up on perfs to 500 psi. Spotted 180 sx class C cmt @ 545' & circulated to surface. Rigged down and moved off. 05/23/18 Moved in backhoe and welder. Dug out cellar. Cut off well head. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.

Spud Date:

Rig Release D

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By **5/21/2019**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):