Submit 1 Copy To Appropriate Districts Office District I = (575) 393-616 HOBBS Energy, Minerals and Natural Resources	Form C-103
District I – (575) 393-616 N Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 O 2018	Revised July 18, 2013 WELL API NO.
DISCRETE (3/3) /48-1283 AUG OIL CONCEDIA TION DIVISION	30-025-42628
B11 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 3771 CEIVED 1220 South St. Francis Dr. Santa Fe. NM 87505	5. Indicate Type of Lease STATE ☐ FEE ☐ BLM ▼
1000 Rio Brazos Rd., Aztec, NM-87710 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	NMLC029509A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name
PROPOSALS.)	Maljamar AGI
1. Type of Well: Oil Well Gas Well Other Acid Gas Injection	2
Name of Operator Frontier Field Services, LLC	9. OGRID Number 221115
3. Address of Operator 4200 Skelly DR. ST. 00, TULSA, OK 74135	10. Pool name or Wildcat
4. Well Location	AGI: Wolfcamp
	2100 feet from the EAST line
Section 21 Township 17S Range 32E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
4019 ft (GI)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	_
PULL OR ALTER CASING	JOB
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	
OTHER: OTHER: Subsequ	ent MIT and Bradenhead
13. Describe proposed or completed operations.	•
The MIT and Braden head test were conducted on Thursday, August 9 at 8:30 am.	
1. Initially the starting injection pressure and the annular space pressure between	casing and tubing was 280 psig.
2. Place chart on annular space and began recording annular space pressure.	
 Bled off annular fluid (diesel) to bring observed annular space pressure to zero psig. Slowly raised annular pressure by introducing diesel to the annulus to bring pressure to 600 psig. 	
5. When annulus pressure reached 600 psig closed valves to pumping truck and respectively.	
6. The Frontier Maljamar AGI #2 was injecting TAG at 2147 psig and 106.5° F.	-
7. After 32 minutes bled off annular fluid to reduce observed pressure to zero psi8. Stopped recording TEST COMPLETE.	g.
9. Restored annular pressure to normal.	
The Braden head test was conducted concurrent with the MIT, which included blee while keeping the valves open during the MIT test.	ding off the pressure and monitoring pressure
I hereby certify that the information above is true and complete to the best of my ki	nowledge.
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	and belief.
SIGNATURE KALLY () LEW TITLE Plant MANAges	DATE 8/9/2018
Type or print name Rudy Quiroz E-mail address: rquiroz@akaenerg	•
Type or print name Rudy Quiroz E-mail address: rquiroz@akaenerg For State Use Only	•

